

Filter Shade Selection for Type of Welding

Operation	Electrode Size (mm)	Arc Current (A)	Min Shade	Suggested Shade
Shielded Metal	< 2.5 mm	< 60	7	*
Arc Welding	2.5 - 4mm	60 - 160	8	10
	4 - 6.4mm	160 - 250	10	12
	> 6.4mm	250 - 550	11	14
Gas Metal Welding and Flux Cored Arc Welding		< 60	7	*
		60 - 160	10	11
		160 - 250	10	12
		250 - 500	10	14
Gas Tungsten Arc Welding		< 50	8	10
		50 - 150	8	12
Air Carbon Arc Cutting		150 - 500	10	14
		< 500	10	12
		500 - 1000	11	14
Torch Brazing				3 or 4
Torch Soldering				2
Carbon Arc Welding				14
Gas Welding (plate under 1/8" thick, light)				4 or 5
Gas Welding (plate 1/8" to 1/2" thick, medium)				5 or 6
Gas Welding (plate over 1/2" thick, heavy)				6 or 8
Oxygen Cutting (plate under 1" thick, light)				3 or 4
Oxygen Cutting (plate 1" to 6" thick, medium)				4 or 5
Oxygen Cutting (plate over 6" thick, heavy)				5 or 6

***As a rule of thumb, start with a shade that is too dark to see the weld zone. Then go to a lighter shade which gives sufficient view of the weld zone without going below the minimum. In Oxyfuel Gas Welding or Cutting where the torch produces a high yellow light, it is desirable to use a filter lens that absorbs the yellow or sodium line in the visible light of the operation.**

****This applies to where the actual arc is clearly seen. Experience has shown that lighter filters may be used when the arc is hidden by the work piece.**

Note: Workers with prescription lenses are not exempt from wearing proper eye protection.